

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS NO. MD-988-A

HABS  
MD  
17-CROM,  
2A-

COFFREN HOUSE, STORE  
10007 Croom Road  
Croom  
Prince Georges County  
Maryland

Jack E. Boucher, photographer, March 13th & 20th 1990

- MD-988-A-1 PERSPECTIVE <sup>IE</sup>VIEW OF NORTHEAST (FRONT) AND SOUTHEAST SIDE
- MD-988-A-2 GENERAL VIEW OF NORTHEAST (FRONT) ELEVATION
- MD-988-A-3 NORTHEAST (FRONT) ELEVATION
- MD-988-A-4 NORTHEAST (FRONT) ELEVATION, WITH SCALE
- MD-988-A-5 SOUTHEAST SIDE AND SOUTHWEST REAR
- MD-988-A-6 GENERAL VIEW OF INTERIOR LOOKING SOUTHWEST FROM FRONT DOORWAY
- MD-988-A-7 VIEW OF INTERIOR, WEST REAR CORNER OF STORE (NOTE: SECTION OF COUNTER TO REAR, RIGHT SIDE HOUSES THE CASH DRAWER)
- MD-988-A-8 CASH DRAWER UNDER REAR COUNTER, NOTE BELL MECHANISM TO BACK OF DRAWER
- MD-988-A-9 CASH DRAWER WITH COIN DRAWER REMOVED TO REVEAL SECTIONS TO HOLD DOLLAR BILLS BENEATH
- MD-988-A-10 CASH DRAWER REMOVED AND TURNED ON SIDE TO SHOW WORKINGS OF BELL MECHANISM
- MD-988-A-11 VIEW OF INTERIOR, SOUTH REAR CORNER OF STORE INCLUDING REAR DOORWAY AND PARTIALLY ENCLOSED STAIRWAY TO SECOND FLOOR
- MD-988-A-12 INTERIOR VIEW, SOUTH REAR CORNER OF STORE SHOWING STAIRWAY
- MD-988-A-13 GENERAL INTERIOR VIEW LOOKING NORTHEAST TO THE FRONT OF THE STORE
- MD-988-A-14 INTERIOR VIEW OF NORTHEAST FRONT ENTRYWAY (NOTE: AFTER HOURS MAIL SLOT TO RIGHT AND POST OFFICE TO LEFT)
- MD-988-A-15 INTERIOR VIEW OF POST OFFICE LOCATED IN NORTH CORNER OF STORE
- MD-988-A-16 REAR OF POST OFFICE SHOWING BOXES, WINDOW AND CLOSED CASH DRAWER

- MD-988-A-17 REAR OF POST OFFICE, CASH DRAWER OPEN
- MD-988-A-18 REAR OF POST OFFICE, CASH DRAWER OPEN AND MONEY DRAWER PULLED OUT
- MD-988-A-19 INTERIOR VIEW BEHIND THE NORTHWEST COUNTER, LOOKING NORTHEAST TOWARDS THE POST OFFICE, SHOWING THE BINS/DRAWERS
- MD-988-A-20 INTERIOR VIEW, SECOND FLOOR, LOOKING FROM NORTHEAST FRONT, FINISHED ROOM INTO SOUTHWEST REAR, UNFINISHED STORAGE AREA. STAIRWAY TO LEFT.